



TIMER1 MODULE

Timer1 Module Silicon Errata Sheet

The PIC[®] microcontrollers you have received all exhibit anomalous behavior in their Timer1 modules, as described in this document. They otherwise conform functionally to the descriptions provided in their respective Device Data Sheets and Reference Manuals, as amended by any silicon release errata for particular devices.

Users are encouraged to review the latest Device Data Sheets and errata available for additional information concerning an individual device. These documents may be obtained directly from the Microchip corporate web site, at www.microchip.com.

These issues are expected to be resolved in future silicon revisions of the designated parts.

Silicon issue 1 affects all silicon revisions of the following devices:

- PIC12F609
- PIC12F615
- PIC12F629
- PIC12F675
- PIC14C000
- PIC12HV609
- PIC12HV615
- PIC12F635
- PIC12F683
- PIC16C62A
- PIC16C62B
- PIC16C63
- PIC16C63A
- PIC16C64A
- PIC16C65A
- PIC16C65B
- PIC16C66
- PIC16C67
- PIC16C72
- PIC16C72A
- PIC16C73A
- PIC16C73B
- PIC16C74A
- PIC16C74B
- PIC16C76
- PIC16C77
- PIC16C745
- PIC16C765
- PIC16C773
- PIC16C774
- PIC16C923
- PIC16C924
- PIC16C925
- PIC16C926
- PIC16F72
- PIC16F73
- PIC16F74
- PIC16F76
- PIC16F77
- PIC16F87
- PIC16F88
- PIC16F610
- PIC16HV610
- PIC16F616
- PIC16HV616
- PIC16F627A
- PIC16F628A
- PIC16F630
- PIC16F631
- PIC16F636
- PIC16F639
- PIC16F648A
- PIC16F676
- PIC16F677
- PIC16F684
- PIC16F685
- PIC16F687
- PIC16F688
- PIC16F689
- PIC16F690
- PIC16F716
- PIC16F737
- PIC16F747
- PIC16F767
- PIC16F777
- PIC16F785
- PIC16HV785
- PIC16F818
- PIC16F819
- PIC16F870
- PIC16F871
- PIC16F872
- PIC16F873
- PIC16F873A
- PIC16F874
- PIC16F874A
- PIC16F876
- PIC16F876A
- PIC16F877
- PIC16F877A
- PIC16F882
- PIC16F883
- PIC16F884
- PIC16F886
- PIC16F887
- PIC16F913
- PIC16F914
- PIC16F916
- PIC16F917
- PIC16F946
- PIC17C42A
- PIC17C43
- PIC17C44
- PIC17C752
- PIC17C756
- PIC17C756A
- PIC17C762
- PIC17C766

TIMER1 MODULE

- PIC18C242
- PIC18C252
- PIC18C442
- PIC18C452
- PIC18C601
- PIC18C658
- PIC18C801
- PIC18C858
- PIC18F242
- PIC18F248
- PIC18F252
- PIC18F258
- PIC18F442
- PIC18F452
- PIC18F458
- PIC18F1220
- PIC18F1230
- PIC18F1320
- PIC18F1330
- PIC18F2220
- PIC18F2320
- PIC18F2321
- PIC18F2331
- PIC18F2431
- PIC18F2439
- PIC18F2455
- PIC18F2480
- PIC18F2510
- PIC18F2520
- PIC18F2539
- PIC18F2550
- PIC18F2585
- PIC18F2610
- PIC18F2620
- PIC18F2680
- PIC18F4220
- PIC18F4320
- PIC18F4321
- PIC18F4331
- PIC18F4431
- PIC18F4439
- PIC18F4455
- PIC18F4480
- PIC18F4510
- PIC18F4520
- PIC18F4539
- PIC18F4550
- PIC18F4580
- PIC18F4585
- PIC18F4610
- PIC18F4620
- PIC18F4680
- PIC18F4685
- PIC18F6490
- PIC18F6520
- PIC18F6525
- PIC18F6527
- PIC18F6585
- PIC18F6620
- PIC18F6621
- PIC18F6622
- PIC18F6627
- PIC18F6680
- PIC18F6720
- PIC18F6722
- PIC18F8490
- PIC18F8520
- PIC18F8525
- PIC18F8527
- PIC18F8585
- PIC18F8620
- PIC18F8621
- PIC18F8622
- PIC18F8627
- PIC18F8680
- PIC18F8720
- PIC18F8722
- PIC18F24J10
- PIC18F25J10
- PIC18F44J10
- PIC18F45J10
- PIC18F63J11
- PIC18F63J90
- PIC18F64J11
- PIC18F64J90
- PIC18F65J10
- PIC18F65J11
- PIC18F65J15
- PIC18F65J50
- PIC18F65J90
- PIC18F66J10
- PIC18F66J11
- PIC18F66J15
- PIC18F66J16
- PIC18F66J50
- PIC18F66J55
- PIC18F66J60
- PIC18F66J65
- PIC18F67J10
- PIC18F67J11
- PIC18F67J50
- PIC18F67J60
- PIC18F83J11
- PIC18F83J90
- PIC18F84J11
- PIC18F84J90
- PIC18F85J10
- PIC18F85J11
- PIC18F85J15
- PIC18F85J50
- PIC18F85J90
- PIC18F86J10
- PIC18F86J11
- PIC18F86J15
- PIC18F86J16
- PIC18F86J50
- PIC18F86J55
- PIC18F86J60
- PIC18F86J65
- PIC18F87J10
- PIC18F87J11
- PIC18F87J50
- PIC18F87J60
- PIC18F96J60
- PIC18F96J65
- PIC18F97J60

TIMER1 MODULE

1. Module: Timer1 (Asynchronous Counter)

When writing to the TMR1H register, under specific conditions, it is possible that the TMR1L register will miss a count while connected to the external oscillator via the T1OSO and T1OSI pins.

When Timer1 is started, the circuitry looks for a falling edge before a rising edge can increment the counter. Writing to the TMR1H register is similar to starting Timer1; therefore, the former logic stated

applies any time the TMR1H register is written. If the TMR1H register is not completely written to during the high pulse of the external clock, then the TMR1L register will miss a count due to the circuit operation stated previously. The high pulse of a 32.768 kHz external clock crystal yields a 15.25 μ s window for the write to TMR1H to occur. The amount of instructions that can be executed within this window is frequency dependent, as shown in Table 1 below.

TABLE 1: FREQUENCY DEPENDENT INSTRUCTION EXECUTION AMOUNTS

Fosc	Tcy (μ s)	Tcy within 15.25 μ s
1 MHz	4	3.81
2 MHz	2	7.63
4 MHz	1	15.25
8 MHz	0.5	30.5
16 MHz	0.25	61
20 MHz	0.2	76.25
40 MHz (PIC18)	0.1	152.5

Work around

Operating Conditions: Fosc \geq 4 MHz, no wake-ups from Sleep, Timer1 interrupt enabled, global interrupts enabled.

The code excerpts in Example 1, Example 2 and Example 3 show how the TMR1H register can be updated while the external clock (32.768 kHz) is still on its high pulse.

The importance of the code examples is that the **bold** instructions are executed within the first 15.25 μ s high pulse on the external clock after the Timer1 overflow occurred. This will allow the TMR1L register to increment correctly.

TIMER1 MODULE

EXAMPLE 1: PIC12/PIC14/PIC16 INTERRUPT SERVICE ROUTINE

```
ISR @ 0x004 ; (3-4Tcy), fixed interrupt latency

    MOVWF w_temp ; (1Tcy), save off current W register contents
    MOVF STATUS,w ; (1Tcy), move status register into W register
    MOVWF status_temp ; (1Tcy), save off contents of STATUS register

    BANKSEL PIR ; (2Tcy), choose correct SFR bank
    BTFSS PIR,TMRIF ; (2Tcy), did a Timer1 overflow occur?
    GOTO EXIT ; No

RELOAD
    BSF TMR1H,7 ; (1Tcy) Yes, reload for a 1 second overflow

EXIT
    MOVF status_temp,w ; retrieve copy of STATUS register
    MOVWF STATUS ; restore pre-isr STATUS register contents
    SWAPF w_temp,f ; restore pre-isr W register contents
    SWAPF w_temp,w ; restore pre-isr W register contents
    RETFIE

Total = 11-12 Tcy (if Timer1 overflow occurred)
```

EXAMPLE 2: PIC18 HIGH PRIORITY INTERRUPT SERVICE ROUTINE

```
ISR @ 0x0008 ; (3-4Tcy), fixed interrupt latency

    BRA HIGHINT ; (2Tcy), go to high priority interrupt routine

HIGHINT
    BTFSC PIR,TMRIF ; (1Tcy), did a Timer1 overflow occur?
    BSF TMR1H,7 ; (1Tcy) Yes, reload for a 1 second overflow

    RETFIE FAST

Total = 7-8 Tcy (if Timer1 overflow occurred)
```

EXAMPLE 3: PIC18 LOW PRIORITY INTERRUPT SERVICE ROUTINE

```
ISR @ 0x0018 ; (3-4Tcy), fixed interrupt latency

    MOVFF STATUS,STATUS_TEMP ; (2Tcy), save STATUS register
    MOVFF WREG,WREG_TEMP ; (2Tcy), save working register, refer to note 1
    MOVFF BSR,BSR_TEMP ; (2Tcy), save BSR register, refer to note 1

    BTFSS PIR,TMRIF ; (2Tcy), did a Timer1 overflow occur?
    BRA EXIT ; No

RELOAD
    BSF TMR1H,7 ; (1Tcy) Yes, reload for a 1 second overflow

EXIT
    MOVFF BSR_TEMP,BSR ; restore BSR register, refer to note 1
    MOVFF WREG_TEMP,WREG ; restore working register, refer to note 1
    MOVFF STATUS_TEMP,STATUS ; restore STATUS register
    RETFIE

Total = 12-13 Tcy (if Timer1 overflow occurred)
```

Note: These instructions are required based on the function of the ISR. If the only code in the ISR is to reload Timer1, then they are not required, but may be required if additional code is added.

REVISION HISTORY

Revision A Document (4/2005):

Original version of this document. Silicon issue 1 (Timer1 – Asynchronous Counter).

Revision B Document (9/2005):

Updated the list of affected devices.

Revision C Document (1/2007):

Updated the list of affected devices.

TIMER1 MODULE

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, Linear Active Thermistor, Migratable Memory, MXDEV, MXLAB, PS logo, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2007, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7250
Fax: 86-29-8833-7256

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471-6166
Fax: 81-45-471-6122

Korea - Gumi
Tel: 82-54-473-4301
Fax: 82-54-473-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Penang
Tel: 60-4-646-8870
Fax: 60-4-646-5086

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820